ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

## BBMP ENGINEERING DEPARTMENT

### Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 15 | T Dasarahalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0087, W0022, I0254 | NA | St. Mary's School |
| **Segment No.** | **Total Length (m)** | |
| 15/C-W0087/S042356 | 134.01 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 134.01 | 77.513881 | 13.047774 | 77.513510 | 13.046618 | 9th cross | End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements & Construction of CC drainage works back side of St Mary's School 1st cross, in Dasarahalli in Ward No.15, Dasarahalli | 1500000 | 2017 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | | 015-17-000013 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/76/17-18 | 15/05/2017 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 19/06/2017 | 18/06/2018 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Pavan kumar K | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9972851320 | | |

**Zone:** DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0087, W0022, I0254

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪೂರ್ವ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು